


CIBSE Guide B2 (2016): corrigenda

Corrections to text

Page 2-16 Figure 2.6: the upper right of the four schematics should be labelled '(b)'.

Page 2-19 Figure 2.11: the abbreviation for variable air volume should read 'VAV'.


Page 2-21 Figure 2.14: incorrect schematic; replace by the following:



Page 2-22 Right hand column, paragraph 4: last sentence should read: 'Fire dampers should not be used ...'

Page 2-32 Figure 2.19: caption for (b) should read 'Cross-flow heat exchanger: typical heat transfer 70%'

Page 2-33 Figure 2.22: arrows on left hand side should be reversed, i.e:



Page 2-35 Table 2.14, column 5: units for air leakage per m^2 of duct surface area should read ' $\text{litre}\cdot\text{s}^{-1}$ '

- Page 2-35 Left hand column, paragraph 2, line 2: should read ‘... velocities should be reduced as the size of the duct is reduced ...’
- Page 2-38 Table 2.15: delete columns 2/3/4 in first row of data
- Page 2-43 Text immediately above equation 2.8 should read ‘Equating equations 2.3 and 2.6 ...’
- Page 2-44 Section 2.3.5.5, paragraph 3, line 5: should read ‘... the surface temperature of the ductwork can be maintained sufficiently above ...’
- Page 2-59 Figure 2.27: the lower two schematics should be labelled ‘(g) Outlet in seat back, non-spreading vertical jet’ (left) and ‘(h) Personal adjustable desk outlet’ (right)

CIBSE: 15/05/18